BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents *will not* correct images, please do not report the images to the Image Problem Mailbox.

SOURCE CODE APPENDIX

```
;=====================================================================
;                    Software UART for SPI-to-RS232
;                  for National Semiconductor's COP8SAx
;
;                         Rev 0.1, February 20, 1998
;
;       > Configured for COP8SAC @ 10MHz
;       > Hardware target = COP8-EVAL-HI01 (COP8 Evaluation Board)
;       > Uses "HyperTerminal" under Windows 95
;
;                         by:  Steven Goldman
;                              National Semiconductor
;                              Senior Field Applications Engineer

;
;
;
        .TITLE SPI-232
        .CHIP  8SAC
        .SECT  MAIN,ROM,ABS=0
;
;
;
;
;DECLARATIONS:

          PORTFD  = 0x94          ; PORTF Data Reg
          PORTFC  = 0x95          ; PORTF Config Reg
          PORTFP  = 0x96          ; PORTF Register (Input Only)
          DIPS    = 0x96          ; Dip Switches
          LEDS    = 0xDC          ; LED's
                                  ;
          TAURLOB = 0E6           ; Timer B Reload, Low
          TAURHIB = 0E7           ; Timer B Reload, High
          TIMERLO = 0EA
          TIMERHI = 0EB           ;
          TAURLO  = 0EC           ; Timer A Reload, Low
          TAURHI  = 0ED           ; Timer A Reload, High
                                  ;
          CNTRL   = 0EE
          PSW     = 0EF
          PORTLD  = 0D0
          PORTLC  = 0D1
          PORTLP  = 0D2
          PORTGD  = 0D4
          PORTGC  = 0D5
          PORTGP  = 0D6
          R0      = 0F0
          R1      = 0F1
          TRUN    = 4
          TPND    = 5
          RECREG  = 020         ;REG TO HOLD RECEIVED DATA.
          STKPTR  = 0xFD          ; Stack Pointer
```

```
;=====================================================================
; RECEIVE PORTION
;
;    1/9600 BAUD = 104 uSEC/BIT DECIMAL = 0068 HEX
;    1/2 BIT TIME IS = 52 uSEC = 52 DECIMAL = 0034 HEX.
;
;
;
START:    LD PORTFC, #0x00       ; Setup PortF as INPUT
          LD A, DIPS
          IFEQ A, #0x00          ; Dislay Revision Number
          JMP REVNUM             ;
                                 ;
          IFEQ A, #0x01          ; Receive Routine
          JMP RECROUT            ;
                                 ;
          IFEQ A, #0x02          ; Transmit Routine
          JMP CALLXMIT           ;
                                 ;
          IFEQ A, #0x03          ; Toggles RXD line
          JMP DEBUG1             ;
                                 ;
          IFEQ A, #0x04          ; Transmit "N"
          JMP SEND_N             ;
                                 ;
          LD A, #0xFF            ; Error Trap
          JSR ATOLEDS
          JMP HERE
                                 ;
                                 ;
                                 ;
;
;---------------------------------------------------------------------
;
REVNUM:   LD A, #0x17            ;
          JSR ATOLEDS            ;
          JMP HERE               ;
;
;---------------------------------------------------------------------
;
DEBUG1:   JSR ATOLEDS            ; Displays the Routine Number (3)
          RBIT 0, PORTLC         ; Make sure it is input pin
          SBIT 1, PORTLC         ; Configure RXD pin as OUTPUT
          LD B, #PORTLD
TOGGLE:   SBIT 1, [B]
          RBIT 1, [B]
          JP TOGGLE
;
;---------------------------------------------------------------------
;
RECROUT:  JSR ATOLEDS
          RBIT 0, PSW            ; Disable all interrupts.
          LD SP, #02F
             RC
          LD PORTGC ,#0x08       ; SET UP G1,& G2 AS INPUTS.
          LD PORTLC, #0x0E       ; Set up L0 as input, L1/L3 as output.
            SBIT 1, PORTLD
            RBIT 3, PORTLD
                                 ;
```

```
                                    ;
STRTRX:   CLRA
          RBIT 3, PORTLD
            RBIT TRUN, CNTRL        ; Make sure timer1 is off.
          LD TIMERLO, #0x0E         ; Load Half timer LB
            LD TIMERHI, #0x00       ; Load Half timer HB
SETIMR:   LD TAURLO, #0x62          ; Load Baudrate LB
            LD TAURHI, #0x00        ; Load Baudrate HB
          LD TAURLOB, #0x00         ;
          LD TAURHIB, #0x00         ;
            LD CNTRL, #0xA0
            LD R1, #0x08            ; (n-1) Data bits=8
                                    ;
IDLE:     IFBIT 0, PORTLP
            JP TRIGGER
            JP IDLE
                                    ;
                                    ;
            RBIT 2, PORTLD
TRIGGER:  SBIT 3, PORTLD
                                    ;
CHECK:    SBIT TRUN , CNTRL         ; Start Timer
          RBIT TPND , PSW           ; Reset Interrupt pending flag
CHECK0:   IFBIT TPND , PSW          ; Test Int flag
          JP CONTST
          JP CHECK0
CONTST:   RBIT TRUN, CNTRL          ; Stop the timer
            SBIT TRUN, CNTRL        ; Start the timer
          RBIT TPND , PSW           ; Reset Interrupt Pending flag
            IFBIT 0, PORTLP         ; Test for valid Start Bit
            JP VALSTART
            JP STRTRX
                                    ;
                                    ;
                                    ;
VALSTART: SBIT 2, PORTLD
            RBIT 2, PORTLD
                                    ;
                                    ;
                                    ;
RECEV:                              ;
                                    ;
CHECK1:     IFBIT TPND, PSW         ; Receive bit in the middle
              JP CONT
              JP CHECK1
CONT:       RBIT TRUN, CNTRL        ; Stop the timer
              SBIT TRUN, CNTRL      ; Start the timer
              RBIT TPND, PSW        ;
            SBIT 2, PORTLD          ; Sampling pulse, per bit
            RBIT 2, PORTLD          ;
                                    ;
            LD A, RECREG            ; Load receive buffer
            SC                      ; Assume this was at Ground, then "1"
            IFBIT 0, PORTLP         ; If at +5VDC, then "0"
            RC                      ; Reset Carry is skipped if "1"
            RRCA                    ; Either way, rotate Right
            X A, RECREG             ; Store as latest value
            DRSZ R1                 ; Are we done yet?
            JP RECEV                ; No...get more
```

```
;
FINISH:   SBIT 3, PORTLD          ; Golly! We are almost done
          LD A, RECREG            ; Display byte
          JSR ATOLEDS
          RBIT 3, PORTLD          ; Trigger scope (end of frame)
          JP STRTRX               ; Go get more
;
;
;
;=========================================================================
ATOLEDS:              ; Value must be in Accumulator
                      ;   Since 1=LED Off, "A" must
                      ;   become NOT A (or /A).  Inverted
                      ;   value is then displayed.  Flow
                      ;   returns to caller.
                      ;
                      ;
        IFEQ A, #0X0D           ; If carriage return (0x0D), return.
        RET
        XOR A, #0xFF            ; Invert each bit
        LD B, #LEDS             ;
        X A, [B]                ; Transfer /A to LED's
        LD A, LEDS
        XOR A, #0xFF
        RET                     ;
;
;=========================================================================
;
HERE:     JMP HERE              ; Subroutine used to wait
                                ;    for Reset
                                ;
                                ;
                                ;
;=========================================================================
;
;
;     TRANSMISSION PORTION
;     ------------------------
;     Generic Calling Routine
;
XMIT:                           ; Soft UART Transmit routine
                                ;   Uses L.1 as an output
                                ;   Assumes L.0 is input
                                ;   Supports Half-duplex mode
                                ;
          SBIT 3, PORTLC        ; Set TRIGGER (L.3) as output
          SBIT 1, PORTLC        ; RXD (send to PC)
          RBIT 0, PORTLC        ; TXD (from PC)
          LD TIMERLO, #0x62     ; Setup Timers
          LD TIMERHI, #0x00     ;
          LD TAURLO, #0x62      ;
          LD TAURHI, #0x00      ;
          LD TAURLOB, #0x00     ;
          LD TAURHIB, #0x00     ;
          LD CNTRL, #0xA0       ;
                                ;
          LD R1, #0x08          ; Set for 8 data bits
                                ;
          RBIT 3, PORTLD        ; Set TRIGGER (L.3) LOW for frame sync
```

```
          SBIT 3, PORTLD        ; Set TRIGGER (L.3) HIGH for frame sync
          RBIT 1, PORTLD        ; Transmit Start Bit (0)
          JSR WFOBT             ; Wait For One Bit Time
                                ;
MOREBITS: RRCA                  ; More next bit to "CARRY"
                                ;
          RBIT 1, PORTLD        ; Assume we XMIT "0"
          IFC                   ; Are we wrong?
          SBIT 1, PORTLD        ; Sorry, XMIT "1"
          JSR WFOBT             ; Either way, wait
          DRSZ R1
          JMP MOREBITS
                                ;
SENDSTOP: SBIT 1, PORTLD        ;
          JSR WFOBT             ;
          RET                   ; Return to calling routine
;
;-------------------------------------------------------------------
;
WFOBT:    SBIT TRUN, CNTRL      ; Wait For One Bit Time
          IFBIT TPND, PSW
          JP BT_DONE            ; Get ready for next one
          JP WFOBT
BT_DONE:  RBIT TPND, PSW        ; Reset Timer
          RET                   ; Return to Calling Routine
;
;-------------------------------------------------------------------
;
CALLXMIT: LD LEDS, #0xF8        ;
          LD A, #'C'            ; Transmit "COP8-"
          JSR XMIT              ;
          LD A, #'O'            ;
          JSR XMIT              ;
          LD A, #'P'            ;
          JSR XMIT              ;
          LD A, #'8'            ;
          JSR XMIT              ;
          LD A, #'-'            ;
          JSR XMIT              ;
          JMP CALLXMIT          ; Do it again, & again, & again...
                                ;
                                ;
;
;-------------------------------------------------------------------
;
SEND_N:   LD LEDS, #0xFB        ;
AA:       LD A, #'N'            ;
          JSR XMIT              ;
          JMP AA                ;
;
;-------------------------------------------------------------------
;
;
        .END START
```